

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : C1 of C3
Report Issued Date : May 26, 2015

Report No.: FR531002C


Report Version : Rev. 01




<Radiated Emission>

X plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : C2 of C3
Report Issued Date : May 26, 2015
Report Version : Rev. 01


Report No.: FR531002C






Y plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : C3 of C3
Report Issued Date : May 26, 2015
Report Version : Rev. 01

Report No.: FR531002C