

## Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1



## **Front View**

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50 Page Number : B1 of B2
Report Issued Date : May 24, 2013

Report No.: FR341702C


Report Version : Rev. 01



## <Radiated Emission>



**Low Frequency** 



**High Frequency** 

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50 Page Number : B2 of B2 Report Issued Date : May 24, 2013

Report No.: FR341702C

Report Version : Rev. 01