

Report No. : FA342511

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASH45 Page Number : D1 of D2
Report Issued Date : Jul. 01, 2013

Report Version : Rev. 01







Front of the DUT with Phantom 1 cm Gap



Report No. : FA342511

Back of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASH45 Page Number : D2 of D2 Report Issued Date: Jul. 01, 2013 Report Version : Rev. 01