


Appendix B. Setup Photographs


<Radiated Emission>

E2 Plane

LF







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : B1 of B2
Report Issued Date : May 27, 2013
Report Version : Rev. 01


Report No.: FG342204




Report No. : FG342204

H Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : B2 of B2
Report Issued Date : May 27, 2013
Report Version : Rev. 01