
# Appendix A. Setup Photographs

### <Conducted Emission>

#### Mode 2



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTMLTE Page Number : A1 of A3
Report Issued Date : Jun. 02, 2016
Report Version : Rev. 01

Report No. : FC642110


Report Template No.: BU5-FC15B Version 1.3

## CC Test Report No. : FC642110


### Mode 1

<Radiated Emission>

LF



HF



### SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTMLTE Page Number : A2 of A3
Report Issued Date : Jun. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

C Test Report No.: FC642110

### Mode 4

LF



HF



### SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTMLTE Page Number : A3 of A3
Report Issued Date : Jun. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3