

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B1 of B2
Report Issued Date : Jan. 06, 2012

Report No.: FR1D0806A


Report Version : Rev. 01





Report No.: FR1D0806A

<Radiated Emission>



HF

LF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B2 of B2
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01