

Report No.: FR2D2505A

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUQT57HD Page Number : B1 of B2
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01




Report No. : FR2D2505A

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUQT57HD Page Number : B2 of B2
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01