
# Appendix A. Setup Photographs

### <Conducted Emission>

### Mode 2



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUENERGYJR Page Number : A1 of A3
Report Issued Date : Apr. 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC631106

## <Radiated Emission>

Mode 3

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUENERGYJR Page Number : A2 of A3
Report Issued Date : Apr. 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC631106

CC Test Report No.: FC631106

#### Mode 4

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUENERGYJR Page Number : A3 of A3
Report Issued Date : Apr. 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3