
Appendix A. Setup Photographs


<Radiated Emission>

X Plane for 22H

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A1 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01

Report No.: FG570301


Report No. : FG570301

Z Plane for 24E

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A2 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01


Report No. : FG570301

X Plane for 27L

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIO7II Page Number : A3 of A3
Report Issued Date : Sep. 10, 2015
Report Version : Rev. 01