


Appendix B. Setup Photographs

<Radiated Emission>

H Plane

LF







TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE Page Number : B1 of B2
Report Issued Date : Jun. 14, 2012
Report Version : Rev. 01

Report No.: FG250202






E1 Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUELITE Page Number : B2 of B2
Report Issued Date : Jun. 14, 2012
Report Version : Rev. 01

Report No.: FG250202