


Report No.: FD151304

# Appendix B. Setup Photographs

## <Conducted Emission>

Mode 1~2



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ

Page Number : B1 of B3 Report Issued Date: Jun. 16, 2011 Report Version : Rev. 01







Report No.: FD151304

### <Radiated Emission>

#### Mode 1~2



#### Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ Page Number : B2 of B3
Report Issued Date : Jun. 16, 2011
Report Version : Rev. 01






Report No.: FD151304

#### Mode 4





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBARQ

Page Number : B3 of B3 Report Issued Date : Jun. 16, 2011 Report Version : Rev. 01