




Page Number : A61 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A62 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A63 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A64 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A65 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A66 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A67 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A68 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01

Conducted Band Edge




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL Page Number : A69 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A70 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A71 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A72 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A73 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A74 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A75 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A76 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A77 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A78 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A79 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A80 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A81 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A82 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A83 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A84 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A85 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL Page Number : A86 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A87 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A88 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A89 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A90 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01