

3.5 Band Edge Measurement

#### 3.5.1 Description of Band Edge Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.


#### 3.5.2 Measuring Instruments

See list of measuring instruments of this test report.

#### 3.5.3 Test Procedures

- 1. The EUT was connected to Spectrum Analyzer and Base Station via power divider.
- The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator.
   The path loss was compensated to the results for each measurement.
- 3. The band edges of low and high channels for the highest RF powers were measured. Setting RBW as roughly BW/100.
- 4. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.
- 5. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
  - = P(W) [43 + 10log(P)] (dB)
  - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
  - = -13dBm.

#### 3.5.4 Test Setup



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 39 of 75 Report Issued Date : Jul. 01, 2013

Report No.: FG342511


Report Version : Rev. 01



3.5.5 Test Result (Plots) of Conducted Band Edge

Band :	GSM850	Test Mode :	GSM Link (GMSK)
Correction Factor :	0.24dB	Maximum 26dB Bandwidth :	0.317MHz
Band Edge :	-15.44dBm	Measurement Value :	-15.68dBm

#### Lower Band Edge Plot on Channel 128 (824.2 MHz)



Date: 5.MAY.2013 06:06:36

- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

  For example, -15.68dBm + 0.24dB = -15.44dBm

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 40 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01


**Band Edge:** 

Band :	GSM850	Test Mode :	GSM Link (GMSK)
Correction Factor :	0.24dB	Maximum 26dB Bandwidth :	0.317MHz

**Measurement Value:** 

#### Higher Band Edge Plot on Channel 251 (848.8 MHz)

-14.11dBm



- Date: 5.MAY.2013 06:17:30
- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 41 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01


Report No.: FG342511

-14.35dBm



Band :	GSM1900	Test Mode :	GSM Link (GMSK)
Correction Factor :	0.24dB	Maximum 26dB Bandwidth :	0.317MHz
Band Edge :	-15.14dBm	Measurement Value :	-15.38dBm

#### Lower Band Edge Plot on Channel 512 (1850.2 MHz)



- Date: 6.MAY.2013 04:02:05
- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 42 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

LAB.	FCC RF Test Report

Band :	GSM1900	Test Mode :	GSM Link (GMSK)
Correction Factor :	0.24dB	Maximum 26dB Bandwidth :	0.317MHz
Band Edge :	-16.61dBm	Measurement Value :	-16.85dBm

#### Higher Band Edge Plot on Channel 810 (1909.8 MHz)



- Date: 5.MAY.2013 06:25:59
- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 43 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



Band: WCDMA Band V Test Mode:	RMC 12.2Kbps Link		
	WODIVIA Bariu V	rest wode.	(QPSK)
Correction Factor :	-3.26dB	Maximum 26dB Bandwidth :	4.718MHz
Band Edge :	-30.25dBm	Measurement Value :	-26.99dBm

#### Lower Band Edge Plot on Channel 4132 (826.4 MHz)



Date: 4.MAY.2013 11:02:18

- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 44 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

<b>FCC</b>	RF	Test	Rei	nort
	<i>i \i i</i>	<i>1</i> 03 t	110	JUIL

Band :	WCDMA Band V	Test Mode :	RMC 12.2Kbps Link (QPSK)
Correction Factor :	-3.26dB	Maximum 26dB Bandwidth :	4.718MHz
Band Edge :	-31.48dBm	Measurement Value :	-28.22dBm

#### Higher Band Edge Plot on Channel 4233 (846.6 MHz)



Date: 4.MAY.2013 11:03:01


- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 45 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band II	Test Mode :	RMC 12.2Kbps Link (QPSK)
Correction Factor :	-3.26dB	Maximum 26dB Bandwidth :	4.718MHz
Band Edge :	-31.23dBm	Measurement Value :	-27.97dBm

#### Lower Band Edge Plot on Channel 9262 (1852.4 MHz)



Date: 4.MAY.2013 10:27:31

- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 46 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band II	Test Mode :	RMC 12.2Kbps Link (QPSK)
Correction Factor :	-3.26dB	Maximum 26dB Bandwidth :	4.718MHz
Band Edge :	-28.86dBm	Measurement Value :	-25.60dBm

#### Higher Band Edge Plot on Channel 9538 (1907.6 MHz)



- Date: 4.MAY.2013 10:28:04
- 1. Correction Factor(dB)= 10log(1% Emission BW/RBW)
- 2. Band Edge= Measurement Value + Correction Factor(dB)

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 47 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



### 3.6 Conducted Spurious Emission Measurement

#### 3.6.1 Description of Conducted Spurious Emission Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.

It is measured by means of a calibrated spectrum analyzer and scanned from 30 MHz up to a frequency including its 10<sup>th</sup> harmonic.


#### 3.6.2 Measuring Instruments

See list of measuring instruments of this test report.

#### 3.6.3 Test Procedures

- 1. The EUT was connected to spectrum analyzer and base station via power divider.
- The RF output of EUT was connected to the spectrum analyzer by RF cable and attenuator.
   The path loss was compensated to the results for each measurement.
- 3. The middle channel for the highest RF power within the transmitting frequency was measured.
- 4. The conducted spurious emission for the whole frequency range was taken.
- 5. The RF fundamental frequency should be excluded against the limit line in the operating frequency band.
- 6. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
  - = P(W) [43 + 10log(P)] (dB)
  - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
  - = -13dBm

#### 3.6.4 Test Setup




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45



3.6.5 Test Result (Plots) of Conducted Spurious Emission


Band :	GSM850	Channel:	CH189
Test Mode :	GSM Link (GMSK)	Frequency:	836.4 MHz

#### Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 5.MAY.2013 08:25:26

#### Conducted Spurious Emission Plot between 1GHz ~ 3GHz



Date: 5.MAY.2013 07:36:38


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 49 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




#### Report No. : FG342511

#### Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 5.MAY.2013 07:39:14

#### Conducted Spurious Emission Plot between 7GHz ~ 9GHz




Date: 5.MAY.2013 07:41:08

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 50 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Band:	GSM1900	Channel:	CH661
Test Mode :	GSM Link (GMSK)	Frequency:	1880.0 MHz

#### Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 5.MAY.2013 07:09:02

#### Conducted Spurious Emission Plot between 1GHz ~ 3GHz




Date: 5.MAY.2013 07:15:03

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 51 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Report No. : FG342511

#### Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 5.MAY.2013 07:20:58

#### Conducted Emission Plot between 7GHz ~ 13.6GHz




Date: 5.MAY.2013 07:23:06

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 52 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



Report No. : FG342511

#### Conducted Spurious Emission Plot between 13.6GHz ~ 19.1GHz




Date: 5.MAY.2013 07:25:30

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 53 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Band :	WCDMA Band V	Channel:	CH4182
Test Mode :	RMC 12.2Kbps Link (QPSK)	Frequency:	836.4 MHz

#### Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 4.MAY.2013 11:00:19

#### Conducted Spurious Emission Plot between 1GHz ~ 3GHz



Date: 4.MAY.2013 10:56:28


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 54 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Report No. : FG342511

#### Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 4.MAY.2013 10:57:27

#### Conducted Spurious Emission Plot between 7GHz ~ 9GHz




Date: 4.MAY.2013 10:58:28

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 55 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Band :	WCDMA Band II	Channel:	CH9400
Test Mode :	RMC 12.2Kbps Link (QPSK)	Frequency:	1880.0 MHz

#### Conducted Spurious Emission Plot between 30MHz ~ 1GHz



Date: 4.MAY.2013 10:44:00

#### Conducted Spurious Emission Plot between 1GHz ~ 3GHz



Date: 4.MAY.2013 10:43:00


SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 56 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01




Report No. : FG342511

#### Conducted Spurious Emission Plot between 3GHz ~ 7GHz



Date: 4.MAY.2013 10:45:54

#### Conducted Spurious Emission Plot between 7GHz ~ 13.6GHz




Date: 4.MAY.2013 10:47:06

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 57 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



Report No. : FG342511

#### Conducted Spurious Emission Plot between 13.6GHz ~ 19.1GHz



Date: 4.MAY.2013 10:48:19

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 58 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

# 3.7 Field Strength of Spurious Radiation Measurement

#### 3.7.1 Description of Field Strength of Spurious Radiated Measurement

The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitter power (P) by a factor of at least 43 + 10 log (P) dB. The spectrum is scanned from 30 MHz up to a frequency including its 10th harmonic.

Report No.: FG342511

#### 3.7.2 Measuring Instruments

See list of measuring instruments of this test report.

#### 3.7.3 Test Procedures

- 1. The EUT was placed on a rotatable wooden table with 0.8 meter above ground.
- 2. The EUT was set 3 meters from the receiving antenna, which was mounted on the antenna tower.
- 3. The table was rotated 360 degrees to determine the position of the highest spurious emission.
- 4. The height of the receiving antenna is varied between one meter and four meters to search the maximum spurious emission for both horizontal and vertical polarizations.
- 5. Make the measurement with the spectrum analyzer's RBW = 1MHz, VBW = 3MHz, taking the record of maximum spurious emission.
- 6. A horn antenna was substituted in place of the EUT and was driven by a signal generator.
- 7. Tune the output power of signal generator to the same emission level with EUT maximum spurious emission.
- 8. Taking the record of output power at antenna port.
- 9. Repeat step 7 to step 8 for another polarization.
- The RF fundamental frequency should be excluded against the limit line in the operating frequency band.

Page Number

Report Version

: 59 of 75

: Rev. 01

Report Issued Date: Jul. 01, 2013


- 11. The limit line is derived from 43 + 10log(P) dB below the transmitter power P(Watts)
  - = P(W) [43 + 10log(P)] (dB)
  - = [30 + 10log(P)] (dBm) [43 + 10log(P)] (dB)
  - = -13dBm.
- 12. EIRP (dBm) = S.G. Power Tx Cable Loss + Tx Antenna Gain
- 13. ERP (dBm) = EIRP 2.15




Report No. : FG342511

#### 3.7.4 Test Setup

#### For radiated emissions from 30MHz to 1GHz



#### For radiated emissions above 1GHz



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 60 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



3.7.5 Test Result of Field Strength of Spurious Radiated

Band :	GSM850	Temperature :	24~25°C
Test Mode :	GSM Link (GMSK)	Relative Humidity :	43~44%
Test Engineer :	John Zheng	Polarization :	Horizontal
Pomark :	Spurious emissions within 30-1000MHz	were found more tha	n 20dB below limit line

Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-SZ

: -13DBM HF\_EIRP\_H\_130101 HORIZONTAL Condition

Project : (FG) 342511

Frequency	ERP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	( dB )	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
1672	-42.54	-13	-29.54	-58.84	-43.19	0.57	3.37	Н	Pass
2510	-28.69	-13	-15.69	-54.10	-30.92	0.78	5.16	Н	Pass
3346	-58.27	-13	-45.27	-68.87	-61.91	0.87	6.66	Н	Pass
4182	-53.26	-13	-40.26	-68.02	-57.85	0.97	7.71	Н	Pass
5018	-51.52	-13	-38.52	-69.81	-57.19	1.09	8.91	Н	Pass


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 61 of 75 Report Issued Date: Jul. 01, 2013

Report No.: FG342511

Report Version : Rev. 01

Band :	GSM850	Temperature :	24~25°C
Test Mode :	GSM Link (GMSK)	Relative Humidity :	43~44%
Test Engineer :	John Zheng	Polarization :	Vertical

**Remark:** Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-SZ


Condition : -13DBM HF\_EIRP\_V\_130101 VERTICAL

Project : (FG) 342511

Frequency	ERP	Limit	Over Limit	SPA Reading	S.G. Power	TX Cable loss	TX Antenna Gain	Polarization	Result
(MHz)	(dBm)	(dBm)	( dB )	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
1672	-42.20	-13	-29.20	-55.65	-42.85	0.57	3.37	V	Pass
2510	-29.75	-13	-16.75	-52.78	-31.98	0.78	5.16	V	Pass
3346	-55.23	-13	-42.23	-67.06	-58.87	0.87	6.66	V	Pass
4182	-46.35	-13	-33.35	-61.57	-50.94	0.97	7.71	V	Pass
5018	-50.75	-13	-37.75	-68.20	-56.42	1.09	8.91	V	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 62 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	GSM1900	Temperature :	22~23°C						
Test Mode :	GSM Link (GMSK)	Relative Humidity :	41~42%						
Test Engineer :	Steven Hao	Polarization :	Horizontal						
Remark ·	Spurious emissions within 30-1000MHz	Spurious emissions within 30-1000MHz were found more than 20dB below limit line							



Site : 03CH01-KS

Condition : FCC PART22 24 HF EIRP FACTOR HORIZONTAL


EUT : (FG)342511

Frequency	EIRP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	(dB)	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
3760	-26.07	-13	-13.07	-41.24	-32.45	0.78	7.16	Н	Pass
5640	-28.24	-13	-15.24	-48.86	-36.78	1.04	9.58	Н	Pass
7520	-28.21	-13	-15.21	-51.75	-38.32	1.35	11.46	Н	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 63 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	GSM1900	Temperature :	24~25°C
Test Mode :	GSM Link (GMSK)	Relative Humidity :	43~44%
Test Engineer :	Steven Hao	Polarization :	Vertical
D	0	(	OO ID hada Baddisa

**Remark:** Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS


Condition : FCC PART22 24 HF EIRP FACTOR VERTICAL

EUT : (FG)342511

Frequency	EIRP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	( dB )	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
3760	-29.07	-13	-16.07	-45.69	-35.45	0.78	7.16	V	Pass
5640	-25.85	-13	-12.85	-47.04	-34.39	1.04	9.58	V	Pass
7520	-33.15	-13	-20.15	-55.43	-43.26	1.35	11.46	V	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 64 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band V	Temperature :	22~23°C
Test Mode :	RMC 12.2Kbps Link (QPSK)	Relative Humidity :	41~42%
Test Engineer :	Steven Hao	Polarization :	Horizontal
Remark :	Spurious emissions within 30-1000MHz	were found more tha	n 20dB below limit line.



Frequency (MHz)

Site : 03CH01-KS


Condition : FCC PART22 24 HF EIRP FACTOR HORIZONTAL

EUT : (FG)342511

Frequency	ERP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	( dB )	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
1672	-64.62	-13	-51.62	-63.78	-65.27	0.57	3.37	Н	Pass
2508	-58.93	-13	-45.93	-64.64	-61.16	0.78	5.16	Н	Pass
3344	-57.06	-13	-44.06	-63.70	-60.70	0.87	6.66	Н	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 65 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band V	Temperature :	22~23°C	
Test Mode :	RMC 12.2Kbps Link (QPSK)	Relative Humidity :	41~42%	
Test Engineer :	Steven Hao	Polarization :	Vertical	
Remark :	Spurious emissions within 30-1000MHz were found more than 20dB below limit line.			



Frequency (MHz)

Site : 03CH01-KS


Condition : FCC PART22 24 HF EIRP FACTOR VERTICAL

EUT : (FG)342511

Frequency	ERP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	( dB )	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
1672	-62.89	-13	-49.89	-63.51	-63.54	0.57	3.37	V	Pass
2508	-56.86	-13	-43.86	-65.05	-59.09	0.78	5.16	V	Pass
3344	-55.28	-13	-42.28	-63.73	-58.92	0.87	6.66	V	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 66 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band II	Temperature :	22~23°C	
Test Mode :	RMC 12.2Kbps Link (QPSK)	Relative Humidity :	41~42%	
Test Engineer :	Steven Hao	Polarization :	Horizontal	
Pomark :	Spurious emissions within 30-1000MHz were found more than 20dB below limit line			



Site : 03CH01-KS

Condition : FCC PART22 24 HF EIRP FACTOR HORIZONTAL


EUT : (FG)342511

Frequency	EIRP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	(dB)	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
3760	-49.51	-13	-36.51	-59.42	-55.89	0.78	7.16	Н	Pass
5640	-56.05	-13	-43.05	-64.73	-64.59	1.04	9.58	Н	Pass
7520	-49.93	-13	-36.93	-65.03	-60.04	1.35	11.46	Н	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 67 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band II	Temperature :	22~23°C
Test Mode :	RMC 12.2Kbps Link (QPSK)	Relative Humidity :	41~42%
Test Engineer :	Steven Hao	Polarization :	Vertical
_			

**Remark:** Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition : FCC PART22 24 HF EIRP FACTOR VERTICAL

EUT : (FG)342511

Frequency	EIRP	Limit	Over	SPA	S.G.	TX Cable	TX Antenna	Polarization	Result
			Limit	Reading	Power	loss	Gain		
(MHz)	(dBm)	(dBm)	(dB)	(dBm)	(dBm)	( dB )	(dBi)	(H/V)	
3762	-49.72	-13	-36.72	-60.79	-56.10	0.78	7.16	V	Pass
5642	-44.78	-13	-31.78	-60.48	-53.32	1.04	9.58	V	Pass
7520	-48.29	-13	-35.29	-65.5	-58.40	1.35	11.46	V	Pass

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 68 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

## 3.8 Frequency Stability Measurement

#### 3.8.1 Description of Frequency Stability Measurement

The frequency stability shall be measured by variation of ambient temperature and variation of primary supply voltage to ensure that the fundamental emission stays within the authorized frequency block. The frequency stability of the transmitter shall be maintained within ±0.00025% (±2.5ppm) of the center frequency.

#### 3.8.2 Measuring Instruments

See list of measuring instruments of this test report.

#### 3.8.3 Test Procedures for Temperature Variation

- 1. The EUT was set up in the thermal chamber and connected with the base station.
- With power OFF, the temperature was decreased to -30°C and the EUT was stabilized before testing. Power was applied and the maximum change in frequency was recorded within one minute.
- 3. With power OFF, the temperature was raised in 10°C step up to 50°C. The EUT was stabilized at each step for at least half an hour. Power was applied and the maximum frequency change was recorded within one minute.
- 4. If the EUT cannot be turned on at -30°C, the testing lowest temperature will be raised in 10°C step until the EUT can be turned on.


#### 3.8.4 Test Procedures for Voltage Variation

- 1. The EUT was placed in a temperature chamber at 25±5° C and connected with the base station.
- 2. The power supply voltage to the EUT was varied from BEP to 115% of the nominal value measured at the input to the EUT.
- 3. The variation in frequency was measured for the worst case.



**Report No.: FG342511** 

## 3.8.5 Test Setup



Thermal Chamber

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 70 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

## 3.8.6 Test Result of Temperature Variation

Band :	GSM 850	Channel:	189
Limit (ppm):	2.5	Frequency:	836.4 MHz

	GS		
Temperature (°C)	Freq. Dev. (Hz)	Deviation (ppm)	Result
-30	-46	-0.05	
-20	-43	-0.05	
-10	-42	-0.05	
0	-39	-0.05	
10	-38	-0.04	PASS
20	-35	-0.04	
30	-37	-0.04	
40	-38	-0.04	
50	-39	-0.05	

Band :	GSM 1900	Channel:	661
Limit (ppm):	2.5	Frequency:	1880.0 MHz

	GS		
Temperature (°C)	Freq. Dev. (Hz)	Deviation (ppm)	Result
-30	-31	-0.02	
-20	-28	-0.01	
-10	-26	-0.01	
0	-27	-0.01	
10	-26	-0.01	PASS
20	-29	-0.02	
30	-31	-0.02	
40	-33	-0.02	
50	-34	-0.02	

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 71 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

Band :	WCDMA Band V	Channel:	4182
Limit (ppm) :	2.5	Frequency:	836.4 MHz

	RMC 12		
Temperature (°C)	Freq. Dev. (Hz)	Deviation (ppm)	Result
-30	-8	-0.01	
-20	-6	-0.01	
-10	-7	-0.01	
0	-6	-0.01	
10	8	+0.01	PASS
20	7	+0.01	
30	-7	-0.01	
40	-8	-0.01	
50	8	+0.01	

Band :	WCDMA Band II	Channel:	9400
Limit (ppm):	2.5	Frequency:	1880.0 MHz

	RMC 12		
Temperature (°C)	Freq. Dev. (Hz)	Deviation (ppm)	Result
-30	19	+0.01	
-20	15	+0.01	
-10	17	+0.01	
0	-13	-0.01	
10	-9	+0.01	PASS
20	-11	-0.01	
30	-12	-0.01	
40	-9	+0.01	
50	-11	-0.01	

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 72 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

## 3.8.7 Test Result of Voltage Variation

Band & Channel	Mode	Voltage (Volt)	Freq. Dev. (Hz)	Deviation (ppm)	Limit (ppm)	Result
	GSM	3.7	-35	-0.04		
GSM 850 CH189		BEP	-34	-0.04		
CITIOS		4.2	-37	-0.04		
0014 4000		3.7	-29	-0.02		
GSM 1900 CH661	GSM	BEP	-27	-0.01	2.5	PASS
		4.2	-29	-0.02		
WCDMA Band V CH4182	5110	3.7	7	+0.01		
	RMC 12.2Kbps	BEP	-6	-0.01		
		4.2	-8	-0.01		
WCDMA Band II CH9400		3.7	-11	-0.01		
	RMC 12.2Kbps	BEP	-9	+0.01		
	12.2000	4.2	-12	-0.01		

#### Note:

- 1. Normal Voltage = 3.7V.
- 2. Battery End Point (BEP) = 3.5 V.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 73 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



4 List of Measuring Equipment

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration	Test Date	Due Date	Remark
					Date			
Spectrum Analyzer	R&S	FSP40	100319	9kHz~40GHz	Dec. 29, 2012	May 04, 2013~ May 06, 2013	Dec. 28, 2013	Conducted (TH01-KS)
Thermal Chamber	Ten Billion	TTC-B3S	TBN-960502	N/A	Dec. 29, 2012	May 04, 2013~ May 06, 2013	Dec. 28, 2013	Conducted (TH01-KS)
EMI Test Receiver	R&S	ESCI	100534	9kHz~3GHz	Nov. 08, 2012	May 07, 2013	Nov. 07, 2013	Radiation (03CH01-KS)
Spectrum Analyzer	R&S	FSP30	100400	9kHz~30GHz	Jun. 01, 2012	May 07, 2013	May 31, 2013	Radiation (03CH01-KS)
Bilog Antenna	SCHAFFNER	CBL6112D	23182	25MHz~2GHz	Dec. 07, 2012	May 07, 2013	Dec. 06, 2013	Radiation (03CH01-KS)
Double Ridge Horn Antenna	EMCO	3117	00075959	1GHz~18GHz	Jan. 06, 2013	May 07, 2013	Jan. 05, 2014	Radiation (03CH01-KS)
Amplifier	com-power	PA-103A	161069	1MHz~1GHz	Jun. 01, 2012	May 07, 2013	May 31, 2013	Radiation (03CH01-KS)
Amplifier	Agilent	8449B	3008A02370	1GHz~26.5GHz	Dec. 29, 2012	May 07, 2013	Dec. 28, 2013	Radiation (03CH01-KS)
SHF-EHF Horn	Schwarzbeck	BBHA 9170	9170249	15GHz~40GHz	Nov. 23, 2012	May 07, 2013	Nov. 22, 2013	Radiation (03CH01-KS)
Turn Table	MF	MF7802	N/A	0 ~ 360 degree	N/A	May 07, 2013	N/A	Radiation (03CH01-KS)
Antenna Mast	MF	MF7802	N/A	1 m - 4 m	N/A	May 07, 2013	N/A	Radiation (03CH01-KS)
ESCI TEST Receiver	R&S	ESCI	100724	9kHz~3GHz	Mar. 28, 2013	May 07, 2013	Mar. 27, 2014	Radiation (03CH01-SZ)
Spectrum Analyzer	R&S	FSP30	101362	9kHz~30GHz	Oct. 11, 2012	May 07, 2013	Oct. 10, 2013	Radiation (03CH01-SZ)
Double Ridge Horn Antenna	ETS Lindgren	3117	00119436	1GHz~18GHz	Oct. 12, 2012	May 07, 2013	Oct. 11, 2013	Radiation (03CH01-SZ)
Bilog Antenna	SCHAFFNER	CBL6112B	2614	30MHz~2GHz	Nov. 03, 2012	May 07, 2013	Nov. 02, 2013	Radiation (03CH01-SZ)
Amplifier	ADVANTEST	BB525C	E9007003	9kHz~3GHz Gain 30dB	Mar. 28, 2013	May 07, 2013	Mar. 27, 2014	Radiation (03CH01-SZ)
Amplifier	Yiai	AV3860B	04030	2GHz~26.5GHz	Mar. 28, 2013	May 07, 2013	Mar. 27, 2014	Radiation (03CH01-SZ)
SHF-EHF-Horn	Schwarzbeck	BBHA9170	BBHA917024 9	14GHz~40GHz	Nov. 23, 2012	May 07, 2013	Nov. 22, 2013	Radiation (03CH01-SZ)
Turn Table	EM Electronic	EM 1000	N/A	0 ~ 360 degree	N/A	May 07, 2013	N/A	Radiation (03CH01-SZ)
Antenna Mast	EM Electronic	EM 1000	N/A	1 m - 4 m	N/A	May 07, 2013	N/A	Radiation (03CH01-SZ)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 74 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01



## 5 Uncertainty of Evaluation

#### Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

Measuring Uncertainty for a Level of	2.54
Confidence of 95% (U = 2Uc(y))	2.54

#### **Uncertainty of Radiated Emission Measurement (1 GHz ~ 40 GHz)**

Measuring Uncertainty for a Level of	4.72
Confidence of 95%(U = 2Uc(y))	4.72

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : 75 of 75
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01

# Appendix A. Photographs of EUT

Please refer to Sporton report number EP342511 as below.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : A1 of A1
Report Issued Date : Jul. 01, 2013
Report Version : Rev. 01