Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : A1 of A3
Report Issued Date : Nov. 18, 2014

Report No.: FR4O0904C


Report Version : Rev. 01




<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : A2 of A3
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01

Report No.: FR4O0904C


Report No. : FR4O0904C

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH35II Page Number : A3 of A3
Report Issued Date : Nov. 18, 2014
Report Version : Rev. 01