

Report No.: FR281501A

Appendix B. Setup Photographs

<Conducted Emission>




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO43 Page Number : B1 of B2
Report Issued Date : Aug. 29, 2012
Report Version : Rev. 01




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO43 Page Number : B2 of B2
Report Issued Date : Aug. 29, 2012
Report Version : Rev. 01

Report No.: FR281501A