




Report No.: FC2D2505

Appendix B. Setup Photographs

<Conducted Emission>

Mode 3






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUQT57HD

: B1 of B3 Page Number Report Issued Date: Feb. 22, 2013 Report Version : Rev. 01



Mode 5



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUQT57HD Page Number : B2 of B3
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01

Report No. : FC2D2505






Report No.: FC2D2505


<Radiated Emission>

Mode 5

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUQT57HD

: B3 of B3 Page Number Report Issued Date: Feb. 22, 2013 Report Version : Rev. 01