

## Appendix B. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM

: B1 of B2 Page Number Report Issued Date: May 14, 2015

Report No.: FR532407A


Report Version : Rev. 01




## <Radiated Emission>

## **Z** Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOCAM Page Number : B2 of B2
Report Issued Date : May 14, 2015
Report Version : Rev. 01

Report No.: FR532407A