

Report No. : FA332203

Appendix D. Test Setup Photos





Table and the state of the stat

Right Cheek

Right Tilted







Left Tilted



Front of the DUT with Phantom 1 cm Gap



Back of the DUT with Phantom 1 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUAMOUR Page Number : D1 of D2
Report Issued Date : Apr. 27, 2013
Report Version : Rev. 01










Report No.: FA332203

Right Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUAMOUR Page Number : D2 of D2
Report Issued Date : Apr. 27, 2013
Report Version : Rev. 01