
## 3. Internal Photograph of EUT

Brand Name: BLU / Model Name: S5

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 12 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 13 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 14 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 15 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 16 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 17 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 18 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 19 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 20 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 21 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 22 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 23 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 24 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 25 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 26 of 33
Report Issued Date : Aug. 28, 2018

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 27 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 28 of 33 Report Issued Date : Aug. 28, 2018

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 29 of 33
Report Issued Date : Aug. 28, 2018


Report No.: EP862706



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 30 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 31 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 32 of 33
Report Issued Date : Aug. 28, 2018
Report Version : Rev. 02

Report No.: EP862706



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : 33 of 33
Report Issued Date : Aug. 28, 2018