

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : B1 of B2
Report Issued Date : May 26, 2015
Report Version : Rev. 01


Report No.: FR531002A



## <Radiated Emission>

Y plane

LF



## HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : B2 of B2
Report Issued Date : May 26, 2015
Report Version : Rev. 01

Report No.: FR531002A