



Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : E1 of E2
Report Issued Date Aug. 28, 2018
Report Version : Rev. 02

Report No.: FR862706A


Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : E2 of E2
Report Issued Date Aug. 28, 2018
Report Version : Rev. 02

Report No.: FR862706A

Report Template No.: BU5-FR15CBT Version 2.0