
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUEGXLTE Page Number : A1 of A3
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2


Report No. : FC5D2213

<Radiated Emission>


Mode 1

Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUEGXLTE Page Number : A2 of A3
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2


Report No. : FC5D2213

C Test Report No.: FC5D2213


Mode 3

Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUEGXLTE Page Number : A3 of A3
Report Issued Date : Jan. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.2