
## Appendix D. SAR Test Setup Photos





Report No.: FA581308

**Right Cheek** 








Left Cheek **Left Tilted** 

TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595


Issued Date : Sep. 28, 2015 FCC ID: YHLBLUSTENERGY2 Form version. : 150415 Page D1 of D2




**Report No.: FA581308** 

Front, Test Separation 10 mm


Back, Test Separation 10 mm




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



**Bottom Side, Test Separation 10 mm** 

Page D2 of D2

TEL: 86-755-8637-9589/ FAX: 86-755-8637-9595

FCC ID: YHLBLUSTENERGY2

Issued Date : Sep. 28, 2015 Form version. : 150415