


Report No. : FA241201

Appendix D. Product Photos









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITET Page Number : D1 of D1
Report Issued Date : May 11, 2012
Report Version : Rev. 01



Report No. : FA241201

Appendix E. **Test Setup Photos**



Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITET Page Number : E1 of E1 Report Issued Date: May 11, 2012 Report Version : Rev. 01