
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 3



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUST50HDLTE Page Number : A1 of A2
Report Issued Date : Nov. 06, 2014
Report Version : Rev. 01

Report No. : FC491911


<Radiated Emission>

Mode 3

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUST50HDLTE Page Number : A2 of A2 Report Issued Date : Nov. 06, 2014

Report No. : FC491911

Report Version : Rev. 01