
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZ3 Page Number : A1 of A3
Report Issued Date : Sep. 18, 2015
Report Version : Rev. 01


Report No. : FC582710

C Test Report No. : FC582710


<Radiated Emission>

Mode 1

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZ3 Page Number : A2 of A3
Report Issued Date : Sep. 18, 2015
Report Version : Rev. 01




Mode 3

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZ3 Page Number : A3 of A3
Report Issued Date : Sep. 18, 2015
Report Version : Rev. 01

Report No. : FC582710