

Report No.: FC3D1804

Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : A1 of A2 Report Issued Date: Jan. 13, 2014 Report Version : Rev. 01







<Radiated Emission>

Mode 3

LF



HF



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUDIO55S Page Number : A2 of A2
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01

Report No.: FC3D1804