

## Appendix B. Setup Photographs

## <Conducted Emission>

## Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO5 Page Number : B1 of B2
Report Issued Date : Feb. 18, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.1


Report No.: FR610605-01B




## <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO5 Page Number : B2 of B2
Report Issued Date : Feb. 18, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.1

Report No.: FR610605-01B