
3. Internal Photograph of EUT

Brand Name: BLU / Model Name: VIVO IV

Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 13 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01




Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 14 of 31 Report Issued Date : May 07, 2014


Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 15 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01



Report No.: EP441002




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV

: 16 of 31 Page Number Report Issued Date : May 07, 2014 Report Version : Rev. 01



Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 17 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01

Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 18 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV

: 19 of 31 Page Number Report Issued Date : May 07, 2014 Report Version : Rev. 01




Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 20 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01




Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 21 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01




Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 22 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01




Report No.: EP441002




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV

: 23 of 31 Page Number Report Issued Date : May 07, 2014 Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 24 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01


Report No.: EP441002




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 25 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01




Report No.: EP441002




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 26 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01




TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 27 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 28 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 29 of 31
Report Issued Date : May 07, 2014
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 30 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01



Report No.: EP441002



TEL: 86-755-3320-2398 FCC ID: YHLBLUVIVOIV Page Number : 31 of 31 Report Issued Date : May 07, 2014 Report Version : Rev. 01