


Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJTOUCH Page Number : B1 of B2
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01

Report No. : FR192002





Report No.: FR192002

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJTOUCH Page Number : B2 of B2
Report Issued Date : Oct. 19, 2011
Report Version : Rev. 01