

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLURAVE

Page Number : B1 of B2 Report Issued Date: Jan. 11, 2012


Report No.: FR1D1601B

Report Version : Rev. 01




Report No.: FR1D1601B

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLURAVE Page Number : B2 of B2
Report Issued Date : Jan. 11, 2012
Report Version : Rev. 01