3. Internal Photograph of EUT

Brand Name: BLU / Model Name: Touch book 7.0

Report No.: EP1N1201



TEL: 86-0512-5790-0158


FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK

Page Number : 16 of 31
Report Issued Date : Dec. 06, 2011


Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 17 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK

Page Number : 18 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



Brand Name: BLU / Model Name: Touch book 7.0

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 19 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201




Brand Name: BLU / Model Name: Touch book 7.0

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 20 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 21 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



Brand Name: BLU / Model Name: Touch book 7.0

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK

Page Number : 22 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201




TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK

Page Number : 23 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201




TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK


Page Number : 24 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 25 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 26 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01


Report No.: EP1N1201



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 27 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 28 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 29 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01

Report No.: EP1N1201



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : 30 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK

Page Number : 31 of 31
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01