
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOMHD Page Number : A1 of A3 Report Issued Date: Jan. 08, 2016 Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC5D1603


<Radiated Emission>

Mode 2

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOMHD Page Number : A2 of A3
Report Issued Date : Jan. 08, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No.: FC5D1603


C Test Report No. : FC5D1603

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTUDIOMHD Page Number : A3 of A3
Report Issued Date : Jan. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1