1. External Photograph of EUT

Brand Name: BLU; Model Name: Life Pro

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 1 of 32
Report Issued Date : Sep. 24, 2013



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 2 of 32 Page Number Report Issued Date : Sep. 24, 2013

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 3 of 32 Report Issued Date : Sep. 24, 2013

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 4 of 32 Report Issued Date : Sep. 24, 2013

: Rev. 01

Report Version

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 5 of 32
Report Issued Date : Sep. 24, 2013

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 6 of 32
Report Issued Date : Sep. 24, 2013

2. Photograph of Accessory

Brand Name: BLU; Model Name: Life Pro

Report No.: EP383001

List of Accessory:

List of Accessory.		
Specification of Accessory		
AC Adapter	Brand Name	BLU
	Model Name	US-AH-1000
Battery	Brand Name	N/A
	Model Name	HD336283PLV
Earphone	Signal Line Type	1.4m, non-shielded cable
USB Cable	Signal Line Type	1.0m, non-shielded cable without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (SHENZHEN) INC.Page NumberTEL: +86-755-3320-2398Report Issued I

FCC ID: YHLBLULIFEPRO

Page Number : 7 of 32
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01

Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 8 of 32 Report Issued Date : Sep. 24, 2013


Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO Page Number : 9 of 32 Report Issued Date : Sep. 24, 2013



Report No.: EP383001




TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 10 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01



Report No.: EP383001



TEL: +86-755-3320-2398 FCC ID: YHLBLULIFEPRO

: 11 of 32 Page Number Report Issued Date : Sep. 24, 2013 Report Version : Rev. 01