


Report No.: FA1D1302

Appendix D. Product Photos






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLACECCSPR Page Number : D1 of D1
Report Issued Date : Jan. 10, 2012
Report Version : Rev. 01



Report No.: FA1D1302

Appendix E. Test Setup Photos





Right Cheek







Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLACECCSPR Page Number : E1 of E1
Report Issued Date : Jan. 10, 2012
Report Version : Rev. 01