Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUG9 Page Number : E1 of E2
Report Issued Date : Mar. 01, 2019
Report Version : Rev. 01


Report No.: FR911616B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0


<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUG9 Page Number : E2 of E2
Report Issued Date : Mar. 01, 2019
Report Version : Rev. 01

Report No.: FR911616B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0