

Appendix B. Setup Photographs

<Conducted Emission>

Mode 3



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBROOKLYN Page Number : B1 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01

Report No.: FC2N0504







<Radiated Emission>

Mode 4

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUBROOKLYN Page Number : B2 of B2
Report Issued Date : Dec. 10, 2012
Report Version : Rev. 01

Report No.: FC2N0504