

Report No.: FA090827-02

## Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : D1 of D1
Report Issued Date : May 12, 2011
Report Version : Rev. 02



## Report No.: FA090827-02

## Appendix E. **Test Setup Photos**





**Right Tilted** 

**Right Cheek** 









**Left Tilted** 



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBAQ Page Number : E1 of E1 Report Issued Date: May 12, 2011 Report Version : Rev. 02