3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 LTE


Report No.: EP452209



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 11 of 34
Report Issued Date : Aug. 08, 2014

Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 12 of 34
Report Issued Date : Aug. 08, 2014

Report Version : Rev. 01


Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 13 of 34
Report Issued Date : Aug. 08, 2014


Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 14 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 15 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 16 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 17 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 18 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 19 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 20 of 34
Report Issued Date : Aug. 08, 2014

: Rev. 01


Report Version

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE


Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 22 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01




Report No.: EP452209



TEL: 86-755-3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 23 of 34 Report Issued Date : Aug. 08, 2014


Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 24 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 25 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 26 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 27 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 28 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 29 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 30 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209




TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 31 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 32 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 33 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01

Report No.: EP452209



TEL: 86-755- 3320-2398 FCC ID: YHLBLUSTUD50LTE Page Number : 34 of 34
Report Issued Date : Aug. 08, 2014
Report Version : Rev. 01