

Report No.: FC2N2401

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 1



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH32

: B1 of B2 Page Number Report Issued Date: Dec. 17, 2012 Report Version : Rev. 01






Report No. : FC2N2401


### <Radiated Emission>

#### Mode 4

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH32 Page Number : B2 of B2
Report Issued Date : Dec. 17, 2012
Report Version : Rev. 01