
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : A1 of A3
Report Issued Date : May 11, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC632501


<Radiated Emission>

Mode 1

LF







SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : A2 of A3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC632501


Report No. : FC632501

Mode 4

LF







SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : A3 of A3
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3