

## Report No. : FA381616


## Appendix D. Test Setup Photos






**Right Cheek** 

Right Tilted





Left Cheek

Left Tilted

TEL: 86-029-8860-8767 FCC ID: YHLBLUDASHMUS40 Page Number : D1 of D2
Report Issued Date : Sep. 09, 2013
Report Version : Rev. 01







Report No. : FA381616

Front of the DUT with Phantom 1 cm Gap

Back of the DUT with Phantom 1 cm Gap



Right Side of the DUT with Phantom 1 cm Gap



Left Side of the DUT with Phantom 1 cm Gap



Top Side of the DUT with Phantom 1 cm Gap



Bottom Side of the DUT with Phantom 1 cm Gap

TEL: 86-029-8860-8767 FCC ID: YHLBLUDASHMUS40 Page Number : D2 of D2
Report Issued Date : Sep. 09, 2013
Report Version : Rev. 01