
3. Internal Photograph of EUT

Brand Name: BLU; Model Name: STUDIO 5.5 HD


Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 12 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD

: 13 of 31 Page Number Report Issued Date : Mar. 01, 2016






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 14 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01




Report No.: EP610801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 15 of 31 Report Issued Date : Mar. 01, 2016 Report Version : Rev. 01




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 16 of 31 Report Issued Date : Mar. 01, 2016






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 17 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 18 of 31 Report Issued Date : Mar. 01, 2016 Report Version : Rev. 01




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 19 of 31 Report Issued Date : Mar. 01, 2016




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 20 of 31 Report Issued Date : Mar. 01, 2016




Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 21 of 31 Report Issued Date : Mar. 01, 2016

Report No.: EP610801


Brand Name: BLU; Model Name: STUDIO 5.5 HD



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 22 of 31 Report Issued Date : Mar. 01, 2016 Report Version : Rev. 01



Report No.: EP610801




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 23 of 31 Report Issued Date : Mar. 01, 2016

: Rev. 01


Report Version

Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 24 of 31
Report Issued Date : Mar. 01, 2016


Report No.: EP610801



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 25 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01

Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 26 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01


Report No.: EP610801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 27 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01

Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 28 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01


Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 29 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01



Report No.: EP610801



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 30 of 31 Report Issued Date : Mar. 01, 2016 Report Version : Rev. 01

Report No.: EP610801



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD55HD Page Number : 31 of 31
Report Issued Date : Mar. 01, 2016
Report Version : Rev. 01