

Report No. : FR500914C

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE54 Page Number : C1 of C2 Report Issued Date : Nov. 27, 2015 Report Version : Rev. 01




Report No.: FR5O0914C

<Radiated Emission>

X Plane

LF



${\sf HF}$



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE54 Page Number : C2 of C2
Report Issued Date : Nov. 27, 2015
Report Version : Rev. 01