

Report No.: FA3D1803

Appendix D. SAR Test Setup Photos





Right Cheek


Right Tilted






Left Cheek

Left Tilted





Front, Test Separation 1 cm

Back, Test Separation 1 cm


SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUVIVO48HD Page Number : D1 of D2 Report Issued Date : Jan. 13, 2014

Report Version : Rev. 01



Left Side, Test Separation 1 cm



Report No.: FA3D1803

Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Back, Test Separation 1 cm (with / Headset)

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUVIVO48HD Page Number : D2 of D2
Report Issued Date : Jan. 13, 2014
Report Version : Rev. 01