


Appendix B. Setup Photographs

<Conducted Emission>





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1 Page Number : D1 of D2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report No.: FR761305C


Report Template No.: BU5-FR15CWL Version 2.0




Report No.: FR761305C

<Radiated Emission>

LF





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUS1

Page Number : D2 of D2 Report Issued Date: Jul. 12, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0