


## Appendix E. Setup Photographs

## <Conducted Emission>

## Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : E1 of E2
Report Issued Date Aug. 28, 2018
Report Version : Rev. 02
Report Template No.: BU5-FR15CBT4.0 Version 2.0


Report No.: FR862706B




## <Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUS5 Page Number : E2 of E2
Report Issued Date Aug. 28, 2018
Report Version : Rev. 02
Report Template No.: BU5-FR15CBT4.0 Version 2.0

Report No.: FR862706B