# Appendix A. Setup Photographs

#### <Conducted Emission>

#### Mode 2



Mode 3



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: YHLBLUST50CE Page Number : A1 of A3
Report Issued Date : Sep. 05, 2014

Report No.: FC471004


Report Version : Rev. 01

CC Test Report No. : FC471004


## <Radiated Emission>

Mode 1

LF




HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755- 3320-2398 FCC ID: YHLBLUST50CE Page Number : A2 of A3
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01




### Mode 3

LF



HF



TEL: 86-755- 3320-2398 FCC ID: YHLBLUST50CE Page Number : A3 of A3 Report Issued Date : Sep. 05, 2014

Report Version : Rev. 01