

Appendix D. Product Photos





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSPEEDII

: D1 of D2 Page Number Report Issued Date: Jan. 21, 2013

Report No.: FA2D0601

Report Version : Rev. 01



Antenna Location:



Antenna	Length	Width
WWAN Antenna <tx rx=""></tx>	5.2 cm	3.6 cm
Bluetooth Antenna <tx rx=""></tx>	1.4 cm	0.2 cm
EUT	9.8 cm	5.6 cm

The shortest distance between the Tx antennas		
WWAN Antenna to Bluetooth Antenna	5.6 cm	

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSPEEDII Page Number : D2 of D2 Report Issued Date : Jan. 21, 2013

Report No.: FA2D0601

Report Version : Rev. 01




Report No.: FA2D0601

Appendix E. Test Setup Photos



Right Cheek

Right Tilted







Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSPEEDII Page Number : E1 of E2
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01



FCC SAR Test Report



Back of the DUT with Phantom 1.5 cm Gap (w/headset)

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSPEEDII Page Number : E2 of E2
Report Issued Date : Jan. 21, 2013
Report Version : Rev. 01

Report No.: FA2D0601