
Appendix E. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-86379589 FAX: +86-755-86379595 FCC ID: YHLBLUB100DL Page Number : E1 of E2
Report Issued Date Jun. 03, 2019
Report Version : Rev. 01

Report No.: FR941714C

Report Template No.: BU5-FR15CWL AC MA Version 2.0

<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-86379589 FAX: +86-755-86379595 FCC ID: YHLBLUB100DL Page Number : E2 of E2
Report Issued Date Jun. 03, 2019
Report Version : Rev. 01

Report No.: FR941714C

Report Template No.: BU5-FR15CWL AC MA Version 2.0